



**SILVERTON**

MARINE CORPORATION

AN EMPLOYEE OWNERSHIP COMPANY

# SERVICE BULLETIN

**BULLETIN:** 11-06  
**DATE:** 12-18-06  
**SUBJECT:** 48C and 50C Cabin Entry Door Lock

It has come to Silverton's attention that a part may have been omitted during manufacture that would prevent the cabin entry door from being properly locked closed.

A plastic filler strip in the door track above the door may have not been installed. This filler strip prevents the door from being lifted out of the bottom track. If the filler is missing, it is possible to lift the door and gain access to the cabin even when the door is locked closed.

To determine if the filler is installed, look up into the top track to see a white or black plastic filler strip secured with screws. If the filler is missing, contact Silverton Customer Service for to obtain the filler and have it installed.



Photo #1



Photo #2