



SILVERTON

MARINE CORPORATION AN EMPLOYEE OWNERSHIP COMPANY

SERVICE BULLETIN

BULLETIN: 2-05

DATE: 3/6/2005

SUBJECT: BOW THRUSTER WITH ISOLATED BATTERY SYSTEM

HULL #s: ALL 38SB, 43SB, 48C AND 42C starting with HULL # 239.

It has recently been brought to Silverton's attention of the possible risk that batteries being installed by our dealers in the bow thruster battery compartment are wrong.

To avoid potential concerns, customers should be aware that a sealed AGM type battery must be used in this area in accordance to the manufacturer's specifications.

The CAUTION sticker provided with this letter must be placed in the bow thruster battery compartment in a highly visible area to be in compliance with the manufacturer's specifications.