

SAFETY RECALL

330 SPORT BRIDGE

Silverton Marine Corporation has determined that many 330 Sport Bridge models may have been manufactured with the propeller shaft seals incorrectly installed. 330 Sport Bridges from hull number thirty-one (31) through hull number two hundred forty-four (244) are affected by this recall. If this condition is present on your boat, failure of the shaft log tube is possible. Such a failure could cause immediate and severe flooding, which could result in sinking.

If your 330 Sport Bridge has a hull identification number that falls into the above range it is critical that you have your boat inspected and obtain the necessary repairs if the defect exists. Please contact your Silverton dealer or any authorized Silverton Service Center to have your boat inspected as soon as possible.

Although we apologize for any inconvenience, our primary concern is your safety. If you require any assistance or have any questions, please contact our Customer Service Hotline at 1-800-882-9266.