



**SILVERTON**

MARINE CORPORATION AN EMPLOYEE OWNERSHIP COMPANY

# SERVICE BULLETIN

**BULLETIN: 01-08**

**DATE: 5/13/08**

**SUBJECT: 52 Ovation Navigation Light Sealant**

**HULL #s: 09153 – 101 – 102 – 103 – 104**

Silverton Marine Corporation has discovered that the Navigation lights that are located on the forward corners of the hardtop need to be finished caulked with white silicone sealant. The entire perimeter of the light and the entire perimeter of the aluminum plate on the underside of the light need to be caulked to prevent water from penetrating into the hardtop.



